


**Case Study- "Hell And Back System" (HABS)
 Duvernay- 55 Plugs Milled out in 54.5 Hrs
 SINGLE TRIP/ NO MOTOR STALLS/ NO MFR!**

1 Milling
 BHA



Pre-Run Bit Pics 114.3mm

Post Run
 Bit Pic



Debris Pics- Debris Size on Average Small & Manageable, with the Odd Bigger Plug Piece Circulated out of the Well.

